



Windshield decal Instructions

IMPORTANT



Work in a place sheltered from the sun, wind and dust.



After sticking, wait at least 72 hours before using car wash.



Always stick the decal at temperatures above 10°C / 50°F



Place the vehicle away from the sun, wind and dust.



Clean with clear water **WITHOUT SOAP !**
Dry with a micro-fiber.



Place the stripe upside down on the hood.



Take off a first part of the sticker from its white paper.



Remove the white support until half of the stripe.
Wet the adhesive part of the sticker abundantly.
Use only water **WITHOUT SOAP !**



Remove the 2nd part of the white paper.



Wet the glue part of the stripe abundantly.



Windshield decal Instructions



Wet the windshield abundantly.



The stripe and windscreen must be completely wet. Lay the stripe approximately without seeking to stick it.



Properly stretch and position the stripe correctly. The set is wet, you can take it back several times.




Wet the top of the sun visor to protect it from scratches that may be occasioned in the following steps.



Remove all water and air bubbles by pressing with spatula from the middle to the outside.



Mark strongly the stripe at the right of the windshield gasket.



Cut along the joint with a cutter.



Remove the excess of the stripe.



Windshield decal Instructions



Spend 10 minutes to remove the last bubbles. Do not hesitate to heat the stripe with a heat gun or a hair dryer to eliminate the most recalcitrant bubbles.

IMPORTANT

The windshield decal was placed with water, therefore respect the following 3 points:



In sunny weather, allow the stripe to dry for at least 1 to 2 hours before using the vehicle.



If the weather is rainy, allow the stripe to dry overnight before using the vehicle.



After sticking, wait at least 72 hours before using car wash.

